


Curb Boxes – 5614RL

Curb Box Repair Lid Only



- Brass components conform to ASTM B62 and ASTM B584, UNS C83600 -85-5-5-5 (latest revision)
- Repair Lid made of Cast Iron per ASTM A48, Class 25
- Coated with black dip
- Made in the United States of America



P.O. Box 508
Dubuque, IA 52004-508

1-800-292-2737
1-800-832-9296
7:00 a.m. – 5:00 p.m., CST

sales@aymcdonald.com
www.aymcdonald.com

A.Y. McDonald considers the information on this assembly drawing correct when published. Item and option availability, including specifications, are subject to change without notice.