


## Copper Ground Clamps - Cable Adaptor




- ▶ For Connecting Ground Wire to Water Pipe, Copper Tubing & Ground Rod
- ▶ Standard Collar and Pressure Bar Grip Adaptor decreases chances of grounding conductors being pulled out
- ▶ Cast of High Strength High Conductivity Copper Alloy
- ▶ Steel Set Screws are Zinc Plated for Corrosion Resistance

Dimensions = Inches

Cat. No.	Pipe Range	Wire Range		Box Qty
		Min	Max	
91670	1/2 - 1	8 SOL	4 STR	10
91672	1-1/4 - 2	8 SOL	4 STR	10

## Copper Ground Clamps - Cable Adaptor - Top Mount




- ▶ For Connecting Ground Wire to Water Pipe, Copper Tubing & Ground Rod
- ▶ Standard Collar and Pressure Bar Grip Adaptor decreases chances of grounding conductors being pulled out
- ▶ Pressure Bar Swings 360° for Easy Alignment
- ▶ Cast of High Strength High Conductivity Copper Alloy
- ▶ Steel Set Screws are Zinc Plated for Corrosion Resistance

Dimensions = Inches

Cat. No.	Pipe Range	Wire Range		Box Qty
		Min	Max	
91680	1/2 - 1	10 SOL	6 SOL	10
91682	1-1/4 - 2	10 SOL	6 SOL	10

## Copper Ground Clamps - Serrated Collar - Cable Adaptor



- ▶ For Connecting Armored Cable/Ground Wire to Water Pipe, Copper Tubing, & Ground Rod
- ▶ Serrated Collar and Adaptor Swings 360° for easy alignment
- ▶ Cast of High Strength High Conductivity Copper Alloy
- ▶ Steel Set Screws are Zinc Plated for Corrosion Resistance

Dimensions = Inches

Cat. No.	Pipe Range	Wire Range		Dimensions			Screw size		Box Qty
		Min	Max	Length	Depth	Height	Top	Side	
91690	1/2 - 1	8 STR	4/0 STR	2.32	.75	1.44	1/4-20 x .63"	1/4-20 x 1.5"	10
91692	1-1/4 - 2	8 STR	4/0 STR	3.54	.83	2.13	1/4-20 x .63"	5/16-18 x 2"	10
91694	2-1/2 - 4	8 STR	4/0 STR	5.95	.98	2.95	1/4-20 x .63"	5/16-18 x 4"	25
91696	4-1/2 - 6	8 STR	4/0 STR	8.09	.94	4.19	1/4-20 x .63"	5/16-18 x 5"	25