



COMPLETED ASSEMBLY



Item Qty.		Part Number	Description
1	4	BF304A	BOLTED FLANGE PLUG
2	4	BF306	3/8-16 X 3" HHCS
3	1	BF201BD	B.F. BACK PLATE B.D.
4	4	BF300GR	3" B.F. GASKET
5	1	BF200G	2" B.F. GASKET
6	1	V20157	1-1/2" TANK FLANGE
7	4	V20018	3/8" LOCK WASHER
8	4	V20019	3/8-16 HEX NUT



AUG 27, 1998

THIS DRAWING AND ALL INFORMATION
CONTAINED THEREON ARE THE EXCLUSIVE
PROPERTY OF BANJO CORPORATION.
UNLESS SPECIFICALLY NOTED, THIS
DRAWING AND ITEMS SHOWN ON THIS
DRAWING ARE SUBJECT TO CHANGE
AT ANY TIME.



BANJO CORPORATION
150 BANJO DR. * CRAWFORDSVILLE, IN 47933

PART NO.

BF150BD

TITLE **1-1/2" BLIND HOLE
BOTTOM DRAIN TANK FLANGE**